A subsidiary of BMW AG

BMW of North America, LLC Press Information

For Release: March 1, 2005

Contact: David J. Buchko Product Communications Manager 201-307-3789 / dave.buchko@bmwna.com

> William Scully BMW Product Communications Specialist 201-307-3790 / william.scully@bmwna.com

2006 BMW 3 SERIES SEDANS: Key differences between U.S. & European models

General

 Initial U.S. models are 325i and 330i; initial European models are 320i, 325i, 330i and 320d

Powertrain

- All U.S. models are 6-cylinder gasoline, vs. 4- and 6-cylinder gasoline and 4cylinder diesel for Europe
- U.S. 325i has 3.0-liter engine, vs. 2.5-liter for European 325i
- Sequential Manual Gearbox (SMG) available only on 330i in U.S., vs. wider availability in Europe

Company BMW of North America, LLC

BMW Group Company

Mailing address PO Box 1227 Westwood, NJ 07675-1227

Office address 300 Chestnut Ridge Road Woodcliff Lake, NJ 07677-7731

> Telephone (201) 307-3606

Fax (201) 307-3607

> Internet bmwusa.com

- Equipment
 - Features standard on U.S. models, not universally standard in Europe:
 - Rain-sensing windshield wipers
 - Xenon Adaptive headlights standard on U.S. 330i, vs. optional in Europe
 - Dynamic Cruise Control
 - Moonroof
 - Leather-wrapped steering wheel with multifunction controls
 - Automatic climate control with rear passenger vent
 - Front center armrest
 - Rear center armrest
 - Power front seats standard in U.S. 330i, vs. optional in Europe
 - Leatherette upholstery (not available in Europe)
 - Premium lighting (Lighting Package) standard in all 6-cylinder models, therefore standard in U.S.

Equipment (cont.)

- Wood interior trim (alternate wood and aluminum trim at no extra cost)
- Features standard on U.S. models, not universally standard in Europe:
 - Logic 7 audio system standard in U.S. 330i, vs. optional in Europe
 - Preparation for installation of CD changer
- Standard and optional road wheels differ
- Standard and optional tire sizes and speed ratings differ
- Content of Packages (Premium, Sport, Cold Weather) specific to U.S. models
- Telephone systems and vehicle interface differ